

# USAF NDI Reliability Improvement: Lessons Learned



**Karl E. Kraft**  
**AF NDI Office**  
**AFRL/RXSST**







# Shoebox



4 Angles/Box



6 Plates/Box, 24 Fasteners/Plate



# Overview



- **Probability of Detection (POD) Experiment Summary**
- **Comparison**
- **Lessons Learned**
- ***Moving Forward***
- **Summary**



# POD Experiment Summary



	<b>Field 1</b>	<b>Depot 1</b>	<b>Field 2</b>	<b>Depot 2</b>
<b>Dates</b>	2004	2005-06	2005-06	2006-07
<b>Bases</b>	16	3	6	3
<b>A/C</b>		Various		Various
<b>Fighters</b>	12		5	
<b>Cargo/bombers</b>	4		1	
<b>Inspectors</b>	64/62	30	26	92



# POD Equipment Summary



<b>Equipment</b>	<b>Field 1</b>	<b>Depot 1</b>	<b>Field 2</b>	<b>Depot 2</b>
<b>Instrument</b>	Local (19ell or 2000D)	Local (2000D)	Local (2000D)	Provided (2000D+)
<b>Standard</b>	Local	Local	Local	Provided
<b>Probe</b>	Provided	Provided	Provided	Provided
<b>Cable</b>	Provided	Provided	Provided	Provided



# Equipment Variability Study




- **Minimal instrument-to-instrument variation observed**
  - Oscillator Frequency Output
  - Receiver Linearity
  - Voltage Output
- **Less than +/- 2dB response variance observe for all tested probe, cable, and reference standard combinations**
- **Results support human induced variance as dominant factor in manual scan eddy current inspection performance variability**




# Variability Results

## dB Variance – Extreme Combinations





# Performance Variance – Probe Angulations







# Comparison



Issues	Field 1	Depot 1	Field 2	Depot 2
Time Allowed	Shift	2 days	2 days	Shift +
Boxes	3	6	6	7
Procedure (pgs)	C-17 (3)	C-130 (14)/ KC135 (11)	-2 (20)	-2 (15)
Training	None	Yes	Yes	Yes
Assist	None	None	None	first box
Cal	4 div	8 div	8 div	8 div
H-Gain	Low	High	High	High
Thresh	None	1.5 div/4 div	1 div	1 div
LO Comp	None	Yes	Yes	Yes



# Plates Relative Performance



Performers	Rank (Best =10)
Depot 2: ALC2	10
Depot 1: ALC2, Depot1: ALC1, Field 2, Depot 2: ALC1	9
Depot 2 Overall	8
Depot 1 Overall, Depot 2: ALC 3	7
Field 1	3
Depot 1: ALC3	1



# Angles Relative Performance



<b>Performer</b>	<b>Rank (Best = 10)</b>
Depot 2: ALC2	10
Depot 2: ALC1	8
Depot 1: ALC1	7
Depot 2: Overall	6
Depot 1: ALC2	5
Depot 1: Overall	2
Field 2, Depot 2: ALC3	1
Field 1, Depot 1: ALC3	0




# Setups for Field 2, Depot 1 and 2





# Field 1 Setup





# Coating Effects and Notch Response



20, 10 & 5 MIL NOTCHES

BARE



3 MIL



10 MIL



7.5 MIL






# Field 1 Coating Thickness Affect



- 20, 10, and 5 mil notches with Field 1 Setup
- From right to left
  - Bare
  - 3 mil coating
  - 4 mil coating
  - 7.5 mil coating
  - 10 mil coating






# Sensitivity Reduction



## Nonconductive Coating Layer vs Sensitivity, 20 mil Notch









# Infinite Crack/Coating Thickness



- **Field 2, Depot 1 and Depot 2 Setups**
- **Conditions**
  - 80% deflection on 20 mil notch
  - Bare Crack (right)
  - Coated: 3 to 30 mil coating (right to left)
- **All indications off-scale for infinite crack**
  - Crack under 25 and 30 mil coating signals actually 60 and 80% deflection






# Infinite Crack/Coating Thickness



- **Field 1 Setup**
- **Conditions**
  - 40% deflection on 20 mil notch
  - Bare Crack (right)
  - Coated: 3 to 30 mil coating (right to left)
- **Indications off-scale for infinite crack under up to 10 mil coating**







# Fastener Heads




Plate POD should exclude length under fastener






# Crack Under Fastener Head Shadow







# Coil Overlap for 10% Deflection



9 hits in 368 opportunities for cracks under fastener head



15 mil probe/notch overlap for 10% deflection






# Probe/Notch Overlap




**Overlap for 10% Response**  
**80% Standardization from 20 mil Notch**  
**0.125 inch Diam Shielded Probe, 200 KHz**







# Fatigue Crack Tip Overlap





# Gap Edge Guide and Crack Tip




- 0.125 Inch Dia Probe
- 0.110 Gap between edge guide and crack tip
- 10% Deflection

CRACK TIP





# Overlap to Saturation






# Distributions of Responses



## Histograms of Crack Responses





# Cracks Less than 0.015 Beyond Fastener




- **19 Cracks too short to get 10% minimum based upon laboratory experiments on notches and infinite crack tip overlap requirements**
  - **9 smallest cracks without one hit in 828 attempts**
  - **9 hits combined from 4 largest cracks beneath heads in 368 attempts**
  - **69 hits combined from next 6 cracks in 552 attempts**
  - **Overall of 78 hits in 1748 attempts for cracks less than 0.015 beyond fastener**
  - **Only 1/4 of misses represented by cracks 0.015 or more beyond fastener**



# Subsurface Crack Simulation



- 80% Deflection Bare 20 mil notch
- Infinite crack
  - 20 mil Aluminum top cover
  - ~10% downward deflection





# Common Errors



- **Unfamiliar with procedure**
- **Read procedure once and then did not refer back to procedure for critical steps**
- **Unfamiliar with Nortec 2000D**
- **Unfamiliar with Load Default steps (rotate SmartKnob to “Confirm”)**
- **Not familiar with effect of H-Gain adjustment (sometimes they called it High Gain as opposed to horizontal)**
- **Failure to tape probe**
- **Failure to establish regular scan pattern**
- **Scanning angles in only one direction**
- **Failure to maintain contact with protruding fastener while scanning around holes**
- **Failure to scan clockwise and counterclockwise around fastener holes**
- **Calibration for angles over taped notches**
- **Calibration for plates over bare notches (no compensation)**



# Common Errors (Cont'd)



- **Failure to regularly check calibration**
- **Failure to maintain signal between right and left sides of screen (angles)**
  - **Excessive H-Gain**
  - **Failure to maintain probe 90 degrees to surface**
- **Assumed tape on probe compensates for liftoff due to paint on part**
- **Inspected flats as well as radius of angles**
- **Interpreted shading meant that open area between fasteners required inspection**
- **Set display erase to 0.5 sec instead of 2-3 sec**
  - **Made it difficult to identify amplitude of signal relative to null point**
  - **Made it difficult for them to view display and to ensure coverage while scanning probe**
- **Failure to erase screen or use Display Erase regularly making it difficult to identify location of signal**
- **Failure to post cal**



# Where's the Dot?







# Current Documentation



## Depot 2

Inspector # _____	Date & Shift _____	D <input type="checkbox"/> S <input type="checkbox"/> G <input type="checkbox"/>	Red <input type="checkbox"/> Blue <input type="checkbox"/>
Post Inspection Cal. Response (Lab. Standard) 20 mil slot: _____ 10 mil slot: _____ 5 mil slot: _____		Post Inspection Cal. Response (Master Standard) 30 mil slot: _____ 20 mil slot: _____ 10 mil slot: _____	
How often was recalibration accomplished? _____ <b>Note each time on comments sheet.</b>			
Does the inspector use some method to keep track of which locations have been inspected?			Yes <input type="checkbox"/> No <input type="checkbox"/>
Lighting conditions Good <input type="checkbox"/> Average <input type="checkbox"/> Poor <input type="checkbox"/>		Area conditions Comfortable <input type="checkbox"/> Hot <input type="checkbox"/> Cold <input type="checkbox"/> Dry <input type="checkbox"/> Quiet <input type="checkbox"/> Humid <input type="checkbox"/> Noisy <input type="checkbox"/>	
Inspectors Attention Level 10 (Focused) to 1 (Distracted or bored) _____			
Inspectors Behavior 10 (cheerful) to 1 (Stressed) _____			
Observations about the actual inspections _____ _____ _____ _____ _____			
Other observations about the actual inspection (technique, coverage, etc.) _____ _____ _____ _____ _____			
<u>Note the Scan Plan used for:</u>			
Plates on a box - area between rivets			
Rivets on a plate - order of proceeding			
Circumference around rivets - coverage			
Angles			
Index Width			
Noticeable changes during inspection			
order of proceeding and tracking location			
_____ _____ _____ _____ _____			







# Previous Documentation



- Field 1
- Field 2
- Depot 1

**Data Acquisition Sheet** NO [unclear]

Program: \_\_\_\_\_ Unit: \_\_\_\_\_ Inspector: \_\_\_\_\_

Date: \_\_\_\_\_ Time: \_\_\_\_\_

NIS Method: Eds. Control Computer: Netw. 20000 Framework: No Frame

**Conditions**

Well Within TD	UC	High	Low
Inspector Equipped	<input checked="" type="checkbox"/>		
Complete Inspection	<input checked="" type="checkbox"/>		
Optimal CR	<input checked="" type="checkbox"/>		
Unlimited Access	<input checked="" type="checkbox"/>		
Unlimited Visibility	<input checked="" type="checkbox"/>		
Accelerated Inspection	<input checked="" type="checkbox"/>		
Monitored Inspection	<input checked="" type="checkbox"/>		
No Observed Noise	<input checked="" type="checkbox"/>		

Temperature: GC: 80 Future: Inspector's release (if available)

**Please write crack locations**

Specimen	Specimen	Specimen	Specimen	Specimen	Specimen	Specimen
A01	A02	A03	A04	A05	A06	A07
	R7			R20	R25	
					⊕	
	⊕	R9 R26	R24-26	R11		
	R21-23	R28-28	R29-31		⊕	
R1	⊕	R27			R24-29	
		R56		R23		

Document: [unclear] 2004 Doc. # [unclear] - [unclear] Page 1 of 3



# Trends



- **Performance improves with standardized procedures, training, and narrowing range of parameters**
- **Guides improve inspector performance comparing plate to angle results**
- **Relative performance among ALCs is consistent**
- **Field performance looks comparable to ALCs when provided similar experiment constraints**
- **Base POD on crack length available to probe (plates)**
- **Rogue misses occur independent of flaw size – human factors**



# Moving Forward



- **T.O. 33B-1-2 Improvements**
- **Depot Inspector Development / Assessments 2008**
- **Command Wide Training Sep 2008**
- **NDI Sustainment Technology Implementation Center**



# T.O. 33B-1-2



- **Standardized Procedures AF wide**
- **New Work Package format for long term stability and ease of use**
- **Changes to address SECI POD results**
  - **Liftoff compensation (warnings/cautions)**
  - **Optimum screen erase (warnings/cautions)**
  - **Reduced horizontal gain (warnings/cautions)**
  - **Maintenance of signal between right and left boundaries**
  - **Separate work packages for scanning and liftoff**
- **Checklist?**
- **Recurring Training Recommendation**
  - **Annual**
  - **Changes**
- **Not intended for System Manager use without Level 3 coordination**



# Depot Training Issues




- **Development of NDI technicians – 2865 hrs minimum / 5 Methods**
- **Classroom training – 304 hrs minimum**
- **Best POD Performance**
  - **Attended AETC Apprentice Course**
  - **Structured OJT**
  - **Progression: Trainee to Level 1 to Level 2**
  - **Certification managed for technician development**
- **Poorer POD Performance**
  - **Local Classroom Training**
  - **Progression: Trainee to Level 2**
  - **Certification managed for production flexibility**



# Civilian/Military Training/Experience



- **AFSC 2A732 (42732 and 45831)= NAS 410 Trainee**
  - Primarily Level 1 Limited; potential for Level 1 and Level 2 in some methods
- **AFSC 2A752 ( 42752 and 45851)= NAS 410 Level 1**
  - Primarily Level 1; potential for Level 2 in some methods
- **AFSC 2A772 (42772 and 45871)= NAS 410 Level 2**
  - Likely Level 2 in all methods depending on rank – time in service





# Experience Factors



<b>Optimum NAS 410 experience factors to obtain Level 2 in shortest time.</b>	<b>Method Hours</b>	<b>Factors %</b>
<b>PT</b>	<b>200</b>	<b>7</b>
<b>MT</b>	<b>265</b>	<b>9</b>
<b>ET</b>	<b>800</b>	<b>28</b>
<b>RT</b>	<b>800</b>	<b>28</b>
<b>UT</b>	<b>800</b>	<b>28</b>



# Command Wide Training



- **AFMCI 21-108**
- **17 NDI Courses**
  - **Level ½ PT and MT**
  - **Level 1 ET, UT and RT**
  - **Level 2 ET, UT and RT**
  - **Refreshers: PT, MT, ET, UT, RT, ST, and IR**
- **Sep 2008 Completion**





# NDI STIC



- **Support Sustainment Technology Process IPT**
- **Centrally Managed Programs: Aging Aircraft**
- **Transition Technology to improve NDI for AFS-TWG**
- **Members: AFNDIO, AFRL/RXLP, AFRL/RXSA, ALC Mgrs, and MAJCOM Functionals**
- **Funding**
  - **RXLP: \$200K**
  - **DTMP: \$1.1M**




# RXLP Funding




- **PODs**
  - **Depot: Angles using Wide Field Coil**
  - **Field: Plates and Angles (WFC) Using QAPA Protocol**
- **MAUS V Scanner Durability Improvement**
- **UT and Eddy Current Arrays**



# Current Approach/Probe




Scan back and forth  
across radius  
indexing 0.125 on  
each pass.






# New Approach



Gently mash probe into radius and slide down the length of the spar.



# Wide Field Probe



New generation flexible or conformal probe.



# Probe Benefits



- **Reduce human factors**
  - **Coverage**
  - **Probability of Inspection**
- **Improved POD**
- **Productivity**
- **Confidence across the board**



# Depot Demonstration



- **Measure POD improvement using wide field coil**
- **Funding: FY08 \$200K AFRL/RXLP**
- **Contractors: Universal Technology Corp and Sandia National Laboratories AANC**
- **When: Spring 2008**
- **Where: 3 depots**
- **Who: 10 personnel sample each ALC**
- **1 Day training/practice**
- **2 Days testing (2 hours/inspector)**
- **Needs: Depot support (facilities/labor)**



# Draft Schedule



ID	Task Name	Duration	October	November	December	January	February	March	April	May	June	July
			Oct	Nov	Dec	Jan	Feb	Mar	Apr	May	Jun	Jul
1	Establish Purpose/Benefits	3 days										
2	Draft Task - Contractor	1 day										
3	<b>Coordination</b>	<b>120 days</b>										
9	<b>Draft Procedure T.O. 33B-1</b>	<b>14 days</b>										
13	TDY UniWest	5 days										
14	<b>Standard</b>	<b>50 days</b>										
18	<b>Probes</b>	<b>50 days</b>										
22	<b>Training Plan</b>	<b>4 days</b>										
25	Dry run procedure/POD	1 day?										
26	<b>OC-ALC</b>	<b>5 days</b>										
32	<b>OO-ALC</b>	<b>4 days</b>										
38	<b>WR-ALC</b>	<b>4 days</b>										
44	<b>Sandia Report</b>	<b>85 days</b>										





# Broader Effort



- **Purpose:** Improve inspection reliability of all safety of flight structure inspections
- **Benefits:** Potential for increased productivity, reduced field level inspections and extension of maintenance intervals
- **Applicability:** Safety of Flight Inspections (SOFIs) – NDI
- **Funding:** \$1.1M FY08 DTMP
- **Critical Input:** ASIP Managers identify Safety of Flight Structures and communicate requirements to NDI



# Reliability Improvement Plan



- **Technical Data - Third party review**
  - **Written accuracy**
  - **Witness inspection**
  - **Evaluate potential inspection reliability improvement**
- **Utilize principle contractor / multiple probe developers**
- **Prototypes - validation**
- **Productionization – verification**
- **System Manager implementation**
- **Leverage developments for other MDS's**



# Other Probes





# Initial Prototypes



Edges



Flat Surface





# Key Performance Parameters



Parameter/ Weight (0-1)	Req,t Threshold	Req't Objective	Expected Value	How to Demo	Current Status	How Demo'd	POF
<b>Reliability</b> 1	<b>-25%</b>	<b>-60%</b>	<b>-50%</b>	<b>POD</b>			<b>0.1</b>
<b>Coverage</b> 0.7	<b>90%</b>	<b>100%</b>	<b>95%</b>	<b>Demo</b>			<b>0.1</b>
<b>Efficiency</b> 0.5	<b>25%</b>	<b>100%</b>	<b>50%</b>	<b>Demo</b>			<b>0.1</b>



# Summary



- **Field 1 is not comparable to other PODs due to many factors handicapping performance**
- **Results improved with standardized T.O. 33B-1-2 procedure and training**
- **Relative performance among ALCs is consistent**
- **Progressive inspector development and recurring training is recommended to establish and maintain proficiency**
- **Base POD upon unobstructed crack length for SECI**
- **Radius inspections (angles) should use wide field coil instead of right angle probe**
- **Support NDI STIC POD efforts and projects to reduce human factors – SOFS inspections**



# Questions?

**Karl E. Kraft**

**[Karl.kraft@tinker.af.mil](mailto:Karl.kraft@tinker.af.mil)**

**Phone: 405-734-1881**